Lead Inspection / Risk Assessment Report

Caulfield Environmental
243 Legate Hill Road
Leominster, MA 01453
(978)534-4670 Office/ (978)534-4570 Fax
caulf@comcast.net

St.# 275 Address Mechanic St Apt.

City Marlborough Zip Code 01752

Owner Name: Marlborough Community Development Authority
Owner Address: Housing Rehabilitation Program
Contact Information: 255 Main Street, Marlborough, MA 01752
Client Name (if different from owner):
Client Address: (508) 460-3715

Number of Rooms in Unit 10
Property Type:
Single Family ✓
Multi Family ___ # Units ___
Condominium ___ # Units ___
Day Care ___ Other: ___

Key:	Lead Column
COV	Covered
VB	Vinyl Baseboard
MET	Metal
VR	Vinyl Rep. Window
MR	Metal Rep. Window
NA	Not Accessible
NC	No Coating
Tile	Tile (testing suggested)
DC	Dropped Ceiling

Key:	Delead/ IC Method Column		
CAP	Capped	SCR	Scraped
COV	Covered	DIP	Dipped
ENC	Encapsulated	REM	Removed
MI	Made Intact	REP	Replaced
PRE	Prepared for Enc	REV	Reversed
VR/MR	Vinyl/Metal Rep Window	INT	Intact
SFR	Storm Frame Removed		
⧄	Component Does not Exist		

Laundry in Basement ? Yes or (No)
Finished Space in Basement ? Yes or (No)

Testing Method Used:
Na_2S Exp. Date ___
X-Ray Fluorescence
Model: RMD-LPA-1 Serial # 1923

Comments / Notes

Floor# 1 (this is the level within building of unit being inspected)



Floor# 2



Pb (lead) equal to or greater than 1.0 mg/cm^2 with x-ray fluorescence or positive with Na_2S is **Dangerous.**

XRF Calibration Recorded in Log Book	✓	✓ -Check off when complete
Address verified through USPS	✓	✓ -Check off when complete
Research on Lead-Related History for Address	✓	✓ -Check off when complete

www.state.ma.us/dph/clppp or 800-532-9571

Inspector Name : Christine Caulfield Lic # M-1950 Signature Christine Caulfield Date 02/22/10

ADDRESS: 275 Mechanic St. Apt# — City Marlborough

INSPECTION HISTORY

Determination / Lead Hazards?	Y / N	Inspector Name: _____, Lic# _____ Signature _____
Comprehensive Initial Inspection 02/22/10 / Lead Hazards?	(Y) / N	Inspector Name: C. Caulfield, Lic# M-1950 Signature Christine Caulfield
Comp Initial w/Partial PCAD / Lead Hazards?	Y / N	Inspector Name: _____, Lic# _____ Signature _____
Addendum (add-on to Initial Inspection) / Lead Hazards?	Y / N	Inspector Name: _____, Lic# _____ Signature _____
Addendum as Full Insp. (Lost Docs) / Lead Hazards?	Y / N	Inspector Name: _____, Lic# _____ Signature _____
Walk Through for Ed/Consultation		Inspector Name: _____, Lic# _____ Signature _____

REINSPECTION HISTORY

Visual Portion of Reocc. Reinspection	P / F	Inspector Name: _____, Lic# _____ Signature _____
Visual Portion of Reocc. Reinspection	P / F	Inspector Name: _____, Lic# _____ Signature _____
Dust Taken for Reocc. Reinspection	P / F	Inspector Name: _____, Lic# _____ Signature _____
Dust Taken for Reocc. Reinspection	P / F	Inspector Name: _____, Lic# _____ Signature _____
Dust Taken for Reocc. Reinspection	P / F	Inspector Name: _____, Lic# _____ Signature _____
Visual Portion of Final Reinspection	P / F	Inspector Name: _____, Lic# _____ Signature _____
Visual Portion of Final Reinspection	P / F	Inspector Name: _____, Lic# _____ Signature _____
Dust Taken for Final Reinsp. (No Reocc)	P / F	Inspector Name: _____, Lic# _____ Signature _____

INTERIM CONTROL

Risk Assessment / Urgent Pb. Hazards?	Y / N	R.A. Name: _____, Lic# _____ Signature _____
Dust Taken for Risk Assessment	P / F	R.A. Name: _____, Lic# _____ Signature _____
Visual Portion of Reinspection for Interim Control	P / F	R.A. Name: _____, Lic# _____ Signature _____
Dust Taken for Risk Assessment Reinsp.	P / F	R.A. Name: _____, Lic# _____ Signature _____
Visual Portion of Reinspection for Interim Control	P / F	R.A. Name: _____, Lic# _____ Signature _____
Dust Taken for Risk Assessment Reinsp.	P / F	R.A. Name: _____, Lic# _____ Signature _____
Risk Assessment Recertification / Urgent Pb. Hazards?	Y / N	R.A. Name: _____, Lic# _____ Signature _____
Dust Taken for RA Recertification	P / F	R.A. Name: _____, Lic# _____ Signature _____

POST COMPLIANCE ASSESSMENT DETERMINATIONS

PCAD / Lead Hazards?	Y / N	Inspector Name: _____, Lic# _____ Signature _____
Full Inspection Acting as PCAD / Lead Hazards?	Y / N	Inspector Name: _____, Lic# _____ Signature _____
Visual Portion of PCAD Reinspection	P / F	Inspector Name: _____, Lic# _____ Signature _____
Dust Taken for PCAD Reinspection	P / F	Inspector Name: _____, Lic# _____ Signature _____
Dust Taken for PCAD Reinspection	P / F	Inspector Name: _____, Lic# _____ Signature _____

ADDRESS: 275 Mechanic Street Apt# — City Marlborough

REOCCUPANCY CERTIFICATE HISTORY

Certificate of Reoccupancy Only after High/Mod Risk (# rooms rule)	Inspector Name:_____, Lic#_____ Signature_____
Certificate of Reoccupancy Only after High/Mod Risk (# rooms rule)	Inspector Name:_____, Lic#_____ Signature_____
Certificate of Reoccupancy Only after High/Mod Risk (# rooms rule)	Inspector Name:_____, Lic#_____ Signature_____

COMPLIANCE HISTORY

Letter of Full Initial Compliance No prior history/ No signs of UD	Inspector Name:_____, Lic#_____ Signature_____
Letter of Interim Control No prior Comp. Expires in 1 yr.	Inspector Name:_____, Lic#_____ Signature_____
Recertification of Interim Control Expires 2 yrs from original Interim Control	Inspector Name:_____, Lic#_____ Signature_____
Letter of Full Deleading Compliance Dust wipes if No Reocc.	Inspector Name:_____, Lic#_____ Signature_____
Certificate of Maintained Compliance No Work= No Dust Work = 7 Dust	Inspector Name:_____, Lic#_____ Signature_____
Certificate of Restored Compliance Dust wipes and auth. people	Inspector Name:_____, Lic#_____ Signature_____

COMPLIANCE HISTORY (CONT.)

Certificate of Maintained Compliance No Work= No Dust Work = 7 Dust	Inspector Name:_____, Lic#_____ Signature_____
Certificate of Restored Compliance Dust wipes and auth. people	Inspector Name:_____, Lic#_____ Signature_____
Certificate of Maintained Compliance No Work= No Dust Work = 7 Dust	Inspector Name:_____, Lic#_____ Signature_____
Certificate of Restored Compliance Dust wipes and auth. people	Inspector Name:_____, Lic#_____ Signature_____

OTHER HISTORY: WAIVERS/UD/EPA RRP

Approved CLPPP Waiver Attach to Comp Docs		CLPPP Insp. Name:_____, Lic#_____ Signature_____
Approved CLPPP Waiver Attach to Comp Docs		CLPPP Insp. Name:_____, Lic#_____ Signature_____
UD / DES Visual Reinspection No LOC Issued	P F	Inspector Name:_____, Lic#_____ Signature_____
UD / DES Dust Taken No LOC Issued	P F	Inspector Name:_____, Lic#_____ Signature_____
UD / DES Dust Taken No LOC Issued	P F	Inspector Name:_____, Lic#_____ Signature_____
EPA RRP Visual And Dust No LOC Issued and	P	Inspector Name:_____, Lic#_____ Signature

EXPLANATION OF LEAD INSPECTION / RISK ASSESSMENT REPORT FORM COLUMNS

This page provides general information needed to understand the lead inspection/risk assessment report. However, you should speak with the inspector/risk assessor before you start to do any work on your home.

SIDE

Refers to A, B, C, or D side of the building or room. See the diagram on the cover sheet. The "A" side of the building or room is the side facing the street that gives the property its address (usually, it is the front of the building). Keeping your back to this street, from the "A" side move clockwise to the "B" side on your left, the "C" side opposite you, and the "D" side to the right. Numbering is from left to right.

LOCATION/ SURFACE

Refers to the building component(s) being tested. Some surfaces may be made up of more than one part. For example, "Baseboard" may refer to four separate pieces of wood (one on each wall), but is still considered one surface.

LEAD

The actual lead result. Each surface tested must have a result recorded in the "Lead" column.

- A number shows that the surface was tested with an XRF analyzer. A number (or average number) equal to or greater than 1.0 mg/cm^2 is a dangerous level of lead.
- A "pos" or "neg" shows that the surface was tested with sodium sulfide. "Pos" means that there is a dangerous level of lead.
- "N/A" means that the inspector was not able to test the surface. Unless the owner can get a sample to test, the inspector must assume the surface contains lead and require it to be deleaded, if necessary.
- "MET" or "MR" means that a metal surface was not tested and only needs to be intact, even if it is a leaded surface. However, metal handrails, metal window sills, and metal railing caps, need to be deleaded if they test equal to or greater than 1.0 mg/cm^2, or is marked "N/A."
- For key to abbreviations like "COV", "VB", "VR" or "MR", "NC", "Tile", "DC", see the cover page.
- When a component box is slashed and there are test results above and below the diagonal line, the result on the "bottom" represents results below 5 ft. and the "top" result indicates the test result above 5 ft.

TYPE OF HAZARD

Not all lead paint must be deleaded. This column tells you IF and WHY a surface needs deleading. The deleading standards below may not apply for Interim Controls. Speak to your risk assessor for more information.

- "M/I" circled means that the surface is a moveable/impacted surface and must be deleaded in its entirety.
- "SF" circled indicates that there is a storm frame present which requires the blind stop and exterior sill be deleaded as interior moveable / impacted surfaces.
- "A/M" circled means that the surface is "accessible mouthable" and must be deleaded to a minimum of five feet high, four inches in from the edge or corner.
- "L" circled means that the surface is loose and must, at minimum, be made intact.
- If more than one choice is circled, the rules for deleading may change depending upon what method of deleading you choose. Speak to the inspector for more information.
- "N/A" means the inspector was unable to determine if the surface was a lead hazard. The person doing the deleading must check this surface and follow all the rules for deleading. Speak to the inspector for more information.
- If nothing is circled in the column, then it is likely the surface does not need deleading. Speak to the inspector for more information. Remember, this does not mean the entire surface is lead free, it just does not require deleading in its current condition.

URG HAZ?

This column is only completed during a risk assessment. A risk assessment is an evaluation of a home's suitability for Interim Control. **Only a licensed risk assessor can do a risk assessment, not all inspectors are risk assessors.** If "Y" is circled, then this surface is considered an "Urgent Lead Hazard" and some type of deleading work is required to qualify for Interim Control.

IC DATE

The date the licensed risk assessor determines the surface meets the standards for Interim Control.

IC METH

The deleading method or structural repair done to qualify the surface for Interim Control. Refer to the deleading codes key on the cover page.

DELEAD DATE

The date that the lead inspector reinspects the surface and finds that it has been successfully brought back into compliance.

DELEAD METH

The method used to bring a surface into full compliance. Refer to codes in the Key on the cover page of the PCAD

EXCLUDED SURFACE

The amount of loose paint on a surface as measured by the lead inspector. "N/A" means that the inspector was not able to measure the loose paint, but has determined it is more than the cut-off for moderate risk making intact.

Christine Caulfield	M-1950	Christine Caulfield	02/22/10
Inspector (print)	Lic #	Signature	Date

Risk Assessor (print)	Lic #	Signature	Date

Address of Property: 275 Mechanic St. Apt. # City: Marlborough

ROOM # 1

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls *	0.0	A/M L N/A	Y				
A B C D	Low Walls *	0.1	A/M L N/A	Y				
A B C D	Baseboards	/	A/M L N/A	Y				
A B C D	Chair Rail	0.0	A/M L N/A	Y				
A B C D	Radiator	/	A/M L N/A	Y				
	Floor	0.4	A/M L N/A	Y				
	Ceiling	DC	A/M L N/A	Y				
A B	Door To porch	0.0	A/M L N/A	Y				
C D	Door Casing	0.1	A/M L N/A	Y				
1 2	Door Jamb	0.0	A/M L N/A	Y				
3 4	Threshold	Met	A/M L N/A	Y				
A B	Door slider	0.0	A/M L N/A	Y				
C D	Door Casing	0.1	A/M L N/A	Y				
1 2	Door Jamb	0.2	A/M L N/A	Y				
3 4	Threshold	0.2	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A	Closet Door	/	A/M L N/A	Y				
B	Cl Casing	/	A/M L N/A	Y				
C	Closet Jamb	/	A/M L N/A	Y				
D	Closet Walls	/	A/M L N/A	Y				
	Cl Baseboard	/	A/M L N/A	Y				
1	Closet Pole	/	A/M L N/A	Y				
2	Closet Shelf	/	A/M L N/A	Y				
3	Cl Supports	/	A/M L N/A	Y				
4	Closet Floor	/	A/M L N/A	Y				
	Closet Ceiling	/	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

*B: clapboards: 5.8 mg/cm²

B: pipechase: 0.0 mg/cm²

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.2	A/M L N/A	Y				
C	Win Casing	5.8	A/M L N/A	Y				
D	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	0.0	M/I A/M L N/A	Y				
B	Win Apron	0.2	A/M L N/A	Y				
C	Win Casing	4.3	A/M L N/A	Y				
D	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.0	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	0.0	M/I A/M L N/A	Y				
B	Win Apron	0.2	A/M L N/A	Y				
C	Win Casing	5.9	A/M L N/A	Y				
D	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A B	Fireplace	/	A/M L N/A	Y				
C D	Mantle	/	A/M L N/A	Y				
A B C D	Win Above 5'	/	A/M L N/A	Y				
	Ceiling Molding	/	A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield — M-1950 — Christine Caulfield — 02/22/10
Inspector (print) — Lic # — Signature — Date

Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 275 Mechanic St. Apt. # ——— City: Marlborough

ROOM # 2

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.0	A/M L N/A	Y				
A B C D	Low Walls	0.1	A/M L N/A	Y				
A B C D	Baseboards	/	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
A B C D	Radiator	/	A/M L N/A	Y				
	Floor	tile	A/M L N/A	Y				
	Ceiling	0.2	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	0.0	A/M L N/A	Y				
1 2	Door Jamb	0.2	A/M L N/A	Y				
3 4	Threshold	0.1	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	NC	A/M L N/A	Y				
1 2	Door Jamb	NC	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A	Closet Door	/	A/M L N/A	Y				
B	Cl Casing	0.0	A/M L N/A	Y				
C	Closet Jamb	0.1	A/M L N/A	Y				
D	Closet Walls	0.3	A/M L N/A	Y				
	Cl Baseboard	/	A/M L N/A	Y				
1	Closet Pole	/	A/M L N/A	Y				
2	Closet Shelf	0.2	A/M L N/A	Y				
3	Cl Supports	0.1	A/M L N/A	Y				
4	Closet Floor	CN	A/M L N/A	Y				
	Closet Ceiling	0.1	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

trim on paneled walls: 0.0

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.1	A/M L N/A	Y				
C	Win Casing	0.2	A/M L N/A	Y				
D	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
X2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	0.2	M/I A/M L N/A	Y				
B	Win Apron	0.3	A/M L N/A	Y				
C	Win Casing	0.1	A/M L N/A	Y				
D	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.0	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
X2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.1	A/M L N/A	Y				
C	Win Casing	0.1	A/M L N/A	Y				
D	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.2	M/I A/M L N/A	Y				
X1	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A B	Fireplace	/	A/M L N/A	Y				
C D	Mantle	/	A/M L N/A	Y				
A B C D	Win Above 5'	/	A/M L N/A	Y				
	Ceiling Molding	/	A/M L N/A	Y				
C	shelves	0.2	A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

:hristine Caulfield — M-1950 — Christine Caulfield — 02/22/10
nspector (print) — Lic # — Signature — Date

Risk Assessor (print) — Lic # — Signature — Date
ddress of Property: 275 Mechanic St. Apt. # — City: Marlborough
ROOM # 3

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.1	A/M L N/A	Y				
A B C D	Low Walls	0.1	A/M L N/A	Y				
A B C D	Baseboards	0.0	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
A B C D	Radiator	/	A/M L N/A	Y				
	Floor	Carpet	A/M L N/A	Y				
	Ceiling	0.3	A/M L N/A	Y				
A B	Door to hall	/	A/M L N/A	Y				
C D	Door Casing	0.1	A/M L N/A	Y				
1 2	Door Jamb	0.2	A/M L N/A	Y				
3 4	Threshold	Carpet	A/M L N/A	Y				
A B	Door closet	/	A/M L N/A	Y				
C D	Door Casing	Rem	A/M L N/A	Y				
1 2	Door Jamb	Rem	A/M L N/A	Y				
3 4	Threshold	Carpet	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A	Closet Door	/	A/M L N/A	Y				
B	Cl Casing	0.0	A/M L N/A	Y	Sheetrock			
C	Closet Jamb	Rem	A/M L N/A	Y				
D	Closet Walls	2.1	A/M L N/A	Y				
	Cl Baseboard	9.9	A/M L N/A	Y				
1	Closet Pole	/	A/M L N/A	Y				
2	Closet Shelf	/	A/M L N/A	Y				
3	Cl Supports	2.9	A/M L N/A	Y				
4	Closet Floor	0.3	A/M L N/A	Y				
	Closet Ceiling	0.6	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.1	A/M L N/A	Y				
C	Win Casing	0.3	A/M L N/A	Y				
D	Header Stop	0.1	M/I A/M L N/A	Y				
BM	Int Stops	0.0	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.0	A/M L N/A	Y				
C	Win Casing	0.2	A/M L N/A	Y				
D	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
1	Win Int Sash	/	M/I A/M L N/A	Y				
2	Exterior Sill	/	M/I SF L N/A	Y				
3	Part Bead	/	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	/	M/I L N/A	Y				
A	Window Sill	/	M/I A/M L N/A	Y				
B	Win Apron	/	A/M L N/A	Y				
C	Win Casing	/	A/M L N/A	Y				
D	Header Stop	/	M/I A/M L N/A	Y				
	Int Stops	/	M/I A/M L N/A	Y				
1	Win Int Sash	/	M/I A/M L N/A	Y				
2	Exterior Sill	/	M/I SF L N/A	Y				
3	Part Bead	/	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	/	M/I L N/A	Y				
A B	Fireplace		A/M L N/A	Y				
C D	Mantle		A/M L N/A	Y				
A B C D	Win Above 5'	/	A/M L N/A	Y				
	Ceiling Molding	/	A/M L N/A	Y				
		/	A/M L N/A	Y				
		/	A/M L N/A	Y				
		/	A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield — M-1950 — Christine Caulfield — 02/22/10
Inspector (print) — Lic # — Signature — Date

Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 275 Mechanic St. Apt. # — City: Marlborough

ROOM # 4

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.0	A/M L N/A	Y				
A B C D	Low Walls	0.2	A/M L N/A	Y				
A B C D	Baseboards	/	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
A B C D	Radiator	/	A/M L N/A	Y				
	Floor 0.4	tile	A/M L N/A	Y				
	Ceiling	0.1	A/M L N/A	Y				
A B	Door sides	0.0	A/M L N/A	Y				
C D	Door Casing	0.1	A/M L N/A	Y				
1 2	Door Jamb	0.0	A/M L N/A	Y				
3 4	Threshold	Met	A/M L N/A	Y				
A B	Door sides	0.2	A/M L N/A	Y				
C D	Door Casing	0.0	A/M L N/A	Y				
1 2	Door Jamb	0.1	A/M L N/A	Y				
3 4	Threshold	Met	A/M L N/A	Y				
A B	Door to porch	0.0	A/M L N/A	Y				
C D	Door Casing	0.2	A/M L N/A	Y				
1 2	Door Jamb	0.0	A/M L N/A	Y				
3 4	Threshold	0.1	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A	Closet Door	/	A/M L N/A	Y				
B	Cl Casing	/	A/M L N/A	Y				
C	Closet Jamb	/	A/M L N/A	Y				
D	Closet Walls	/	A/M L N/A	Y				
	Cl Baseboard	/	A/M L N/A	Y				
1	Closet Pole	/	A/M L N/A	Y				
2	Closet Shelf	/	A/M L N/A	Y				
3	Cl Supports	/	A/M L N/A	Y				
4	Closet Floor	/	A/M L N/A	Y				
	Closet Ceiling	/	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.0	A/M L N/A	Y				
C	Win Casing	0.2	A/M L N/A	Y				
D	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
1	Win Int Sash	MR	M/I A/M L N/A	Y				
2	Exterior Sill	MR	M/I SF L N/A	Y				
X3	Part Bead	MR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	MR	M/I L N/A	Y				
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.0	A/M L N/A	Y				
C	Win Casing	0.0	A/M L N/A	Y				
D	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.2	M/I A/M L N/A	Y				
1	Win Int Sash	MR	M/I A/M L N/A	Y				
X2	Exterior Sill	MR	M/I SF L N/A	Y				
3	Part Bead	MR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	MR	M/I L N/A	Y				
A	Window Sill	0.0	M/I A/M L N/A	Y				
B	Win Apron	0.4	A/M L N/A	Y				
C	Win Casing	0.0	A/M L N/A	Y				
D	Header Stop	0.1	M/I A/M L N/A	Y				
	Int Stops	0.0	M/I A/M L N/A	Y				
1	Win Int Sash	MR	M/I A/M L N/A	Y				
2	Exterior Sill	MR	M/I SF L N/A	Y				
X3	Part Bead	MR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	MR	M/I L N/A	Y				
A B	Fireplace	/	A/M L N/A	Y				
C D	Mantle	/	A/M L N/A	Y				
A B C D	Win Above 5'	/	A/M L N/A	Y				
	Ceiling Molding	/	A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield	M-1950	Christine Caulfield	02/22/10
Inspector (print)	Lic #	Signature	Date

Risk Assessor (print) Lic # Signature Date

Address of Property: 275 Mechanic St. Apt. # — City: Marlboorough

ROOM # 5

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.1	A/M L N/A	Y				
A B C D	Low Walls	0.1	A/M L N/A	Y				
A B C D	Baseboards	0.2	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
A B C D	Radiator	/	A/M L N/A	Y				
	Floor	Carpet	A/M L N/A	Y				
	Ceiling	0.1	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	0.2	A/M L N/A	Y				
1 2	Door Jamb	0.1	A/M L N/A	Y				
3 4	Threshold	Carpet	A/M L N/A	Y				
A B	Door	0.1	A/M L N/A	Y				
C D	Door Casing	0.3	A/M L N/A	Y				
1 2	Door Jamb	0.1	A/M L N/A	Y				
3 4	Threshold	Met	A/M L N/A	Y				
A B	Door	.	A/M L N/A	Y				
C D	Door Casing	.	A/M L N/A	Y				
1 2	Door Jamb	.	A/M L N/A	Y				
3 4	Threshold	.	A/M L N/A	Y				
A B	Door	.	A/M L N/A	Y				
C D	Door Casing	.	A/M L N/A	Y				
1 2	Door Jamb	.	A/M L N/A	Y				
3 4	Threshold	.	A/M L N/A	Y				
A	Closet Door	.	A/M L N/A	Y				
B	Cl Casing	.	A/M L N/A	Y				
C	Closet Jamb	.	A/M L N/A	Y				
D	Closet Walls	.	A/M L N/A	Y				
	Cl Baseboard	.	A/M L N/A	Y				
1	Closet Pole	.	A/M L N/A	Y				
2	Closet Shelf	.	A/M L N/A	Y				
3	Cl Supports	.	A/M L N/A	Y				
4	Closet Floor	.	A/M L N/A	Y				
	Closet Ceiling	.	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.2	M/I A/M L N/A	Y				
B	Win Apron	0.1	A/M L N/A	Y				
C	Win Casing	0.0	A/M L N/A	Y				
D	Header Stop	0.1	M/I A/M L N/A	Y				
BAY	Int Stops	0.0	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.0	A/M L N/A	Y				
C	Win Casing	0.4	A/M L N/A	Y				
D	Header Stop	0.2	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
1	Win Int Sash	.	M/I A/M L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.1	A/M L N/A	Y				
C	Win Casing	0.3	A/M L N/A	Y				
D	Header Stop	0.1	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
1	Win Int Sash	.	M/I A/M L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B	Fireplace		A/M L N/A	Y				
C D	Mantle	.	A/M L N/A	Y				
A B C D	Win Above 5'	.	A/M L N/A	Y				
	Ceiling Molding	0.0	A/M L N/A	Y				
		.	A/M L N/A	Y				
		..	A/M L N/A	Y				
		.	A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield — Inspector (print)
M-1950 — Lic #
Christine Caulfield — Signature
02/22/10 — Date

Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 275 Mechanic St. Apt. # ——— City: Marlborough

ROOM # 6

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.1	A/M L N/A	Y				
A B C D	Low Walls	0.0	A/M L N/A	Y				
A B C D	Baseboards	/	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
A B C D	Radiator	/	A/M L N/A	Y				
	Floor	CON	A/M L N/A	Y				
	Ceiling	0.3	A/M L N/A	Y				
A B	Door	0.1	A/M L N/A	Y				
C D	Door Casing	0.0	A/M L N/A	Y				
1 2	Door Jamb	0.2	A/M L N/A	Y				
3 4	Threshold	CON	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A	Closet Door	/	A/M L N/A	Y				
B	Cl Casing	/	A/M L N/A	Y				
C	Closet Jamb	/	A/M L N/A	Y				
D	Closet Walls	/	A/M L N/A	Y				
	Cl Baseboard	/	A/M L N/A	Y				
1	Closet Pole	/	A/M L N/A	Y				
2	Closet Shelf	/	A/M L N/A	Y				
3	Cl Supports	/	A/M L N/A	Y				
4	Closet Floor	/	A/M L N/A	Y				
	Closet Ceiling	/	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.0	A/M L N/A	Y				
C	Win Casing	0.2	A/M L N/A	Y				
D	Header Stop	0.1	M/I A/M L N/A	Y				
	Int Stops	0.0	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	0.3	M/I A/M L N/A	Y				
B	Win Apron	0.1	A/M L N/A	Y				
C	Win Casing	0.0	A/M L N/A	Y				
D	Header Stop	0.2	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	0.4	M/I A/M L N/A	Y				
B	Win Apron	0.1	A/M L N/A	Y				
C	Win Casing	0.0	A/M L N/A	Y				
D	Header Stop	0.1	M/I A/M L N/A	Y				
	Int Stops	0.0	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A B	Fireplace	/	A/M L N/A	Y				
C D	Mantle	/	A/M L N/A	Y				
A B C D	Win Above 5'	/	A/M L N/A	Y				
	Ceiling Molding	/	A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield — M-1950 — Christine Caulfield — 02/22/10
Inspector (print) — Lic # — Signature — Date

Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 275 Mechanic St. Apt. # — City: Marlborough

ROOM # 7

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.1	A/M L N/A	Y				
A B C D	Low Walls	0.2	A/M L N/A	Y				
A B C D	Baseboards	/	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
A B C D	Radiator	/	A/M L N/A	Y				
	Floor	CW	A/M L N/A	Y				
	Ceiling	0.5	A/M L N/A	Y				
A B	Door	0.1	A/M L N/A	Y				
C D	Door Casing	0.2	A/M L N/A	Y				
1 2	Door Jamb	0.1	A/M L N/A	Y				
3 4	Threshold	CW	A/M L N/A	Y				
A B	Door	0.1	A/M L N/A	Y				
C D	Door Casing	0.1	A/M L N/A	Y				
1 2	Door Jamb	0.2	A/M L N/A	Y				
3 4	Threshold	CW	A/M L N/A	Y				
A B	Door	.	A/M L N/A	Y				
C D	Door Casing	.	A/M L N/A	Y				
1 2	Door Jamb	.	A/M L N/A	Y				
3 4	Threshold	.	A/M L N/A	Y				
A B	Door	.	A/M L N/A	Y				
C D	Door Casing	.	A/M L N/A	Y				
1 2	Door Jamb	.	A/M L N/A	Y				
3 4	Threshold	.	A/M L N/A	Y				
A	Closet Door	0.1	A/M L N/A	Y				
B	Cl Casing	/	A/M L N/A	Y				
C	Closet Jamb	0.1	A/M L N/A	Y				
D	Closet Walls	0.5	A/M L N/A	Y				
	Cl Baseboard	9.9	A/M L N/A	Y				
1	Closet Poles	N.C	A/M L N/A	Y				
2	Closet Shelf	9.9	A/M L N/A	Y				
3	Cl Supports	8.6	A/M L N/A	Y				
4	Closet Floor	CW	A/M L N/A	Y				
	Closet Ceiling	0.4	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.1	A/M L N/A	Y				
C	Win Casing	0.2	A/M L N/A	Y				
D	Header Stop	0.1	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	0.3	M/I A/M L N/A	Y				
B	Win Apron	0.1	A/M L N/A	Y				
C	Win Casing	0.0	A/M L N/A	Y				
D	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron		A/M L N/A	Y				
C	Win Casing		A/M L N/A	Y				
D	Header Stop	.	M/I A/M L N/A	Y				
	Int Stops	.	M/I A/M L N/A	Y				
1	Win Int Sash	.	M/I A/M L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B	Fireplace		A/M L N/A	Y				
C D	Mantle	.	A/M L N/A	Y				
A B C D	Win Above 5'	.	A/M L N/A	Y				
	Ceiling Molding	.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield — Inspector (print)
M-1950 — Lic #
Christine Caulfield — Signature
02/22/10 — Date

Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 275 Mechanic St. Apt. # — City: Marlborough

ROOM # 8

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.2	A/M L N/A	Y				
A B C D	Low Walls	0.2	A/M L N/A	Y				
A B C D	Baseboards	/	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
A B C D	Radiator	/	A/M L N/A	Y				
	Floor	2.5	A/M (L) N/A	(Y)				
	Ceiling	0.4	A/M L N/A	Y				
(A) B	Door	0.1	A/M L N/A	Y				
C D	Door Casing	0.1	A/M L N/A	Y				
(1) 2	Door Jamb	0.2	A/M L N/A	Y				
3 4	Threshold	CON	A/M L N/A	Y				
A (B)	Door	Rem	A/M L N/A	Y				
C D	Door Casing	Rem	A/M L N/A	Y				
(1) 2	Door Jamb	Rem	A/M L N/A	Y				
3 4	Threshold	Carpet	A/M L N/A	Y				
A B	Door	.	A/M L N/A	Y				
C D	Door Casing	.	A/M L N/A	Y				
1 2	Door Jamb	.	A/M L N/A	Y				
3 4	Threshold	.	A/M L N/A	Y				
A B	Door	.	A/M L N/A	Y				
C D	Door Casing	.	A/M L N/A	Y				
1 2	Door Jamb	.	A/M L N/A	Y				
3 4	Threshold	.	A/M L N/A	Y				
(A)	Closet Door	Rem	A/M L N/A	Y				
B	Cl Casing	Rem	A/M L N/A	Y				
C	Closet Jamb	Rem	A/M L N/A	Y				
D	Closet Walls	0.7	A/M L N/A	Y				
	Cl Baseboard	0.0	A/M L N/A	Y	Quarter Round			
(1)	Closet Pole	Met	A/M L N/A	Y				
2	Closet Shelf	NC	A/M L N/A	Y				
3	Cl Supports	Met	A/M L N/A	Y				
4	Closet Floor	2.8	A/M (L) N/A	(Y)				
	Closet Ceiling	0.4	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:
A: small boxed in area in closet: 0.0 mg/cm²

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.2	M/I A/M L N/A	Y				
B	Win Apron	0.0	A/M L N/A	Y				
C	Win Casing	0.1	A/M L N/A	Y				
(D)	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.3	M/I A/M L N/A	Y				
(1)	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	0.2	M/I A/M L N/A	Y				
B	Win Apron	0.1	A/M L N/A	Y				
C	Win Casing	0.0	A/M L N/A	Y				
(D)	Header Stop	0.1	M/I A/M L N/A	Y				
	Int Stops	0.0	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
(2)	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	A/M L N/A	Y				
C	Win Casing	.	A/M L N/A	Y				
D	Header Stop	.	M/I A/M L N/A	Y				
	Int Stops	.	M/I A/M L N/A	Y				
1	Win Int Sash	.	M/I A/M L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B	Fireplace	.	A/M L N/A	Y				
C D	Mantle	.	A/M L N/A	Y				
A B C D	Win Above 5'	.	A/M L N/A	Y				
	Ceiling Molding	.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield M-1950 Christine Caulfield 02/22/10
Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic# Signature Date
Address of Property: 275 Mechanic St. Apt. # — City: Marlborough

KITCHEN

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.1	A/M L N/A	Y				
A B C D	Low Walls	0.0	A/M L N/A	Y				
A B C D	Baseboards	0.2	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
A B C D	Radiator	/	A/M L N/A	Y				
	Floor	tile	A/M L N/A	Y	-0.3			
	Ceiling TIN	2.4	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	-0.0	A/M L N/A	Y				
1 2	Door Jamb	0.0	A/M L N/A	Y				
3 4	Threshold	tile	A/M L N/A	Y				
A B	Door sliders	0.1	A/M L N/A	Y				
C D	Door Casing	0.2	A/M L N/A	Y				
1 2	Door Jamb	0.1	A/M L N/A	Y				
3 4	Threshold	Metal	A/M L N/A	Y				
A B	Door Archway	/	A/M L N/A	Y				
C D	Door Casing	0.0	A/M L N/A	Y				
1 2	Door Jamb	0.2	A/M L N/A	Y				
3 4	Threshold	tile	A/M L N/A	Y				
A B	Door to porch 3	0.1	A/M L N/A	Y				
C D	Door Casing	0.1	A/M L N/A	Y				
1 2	Door Jamb	0.2	A/M L N/A	Y				
3 4	Threshold	0.1	A/M L N/A	Y				
A	Closet Door	.	A/M L N/A	Y				
B	Cl Casing		A/M L N/A	Y				
C	Closet Jamb	.	A/M L N/A	Y				
D	Closet Walls	.	A/M L N/A	Y				
	Cl Baseboard	.	A/M L N/A	Y				
1	Closet Pole	.	A/M L N/A	Y				
2	Closet Shelf	.	A/M L N/A	Y				
3	Cl Supports	.	A/M L N/A	Y				
4	Closet Floor	.	A/M L N/A	Y				
	Closet Ceiling	.	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	-0.2	M/I A/M L N/A	Y				
B	Win Apron	0.1	A/M L N/A	Y				
C	Win Casing	0.0	A/M L N/A	Y				
D	Header Stop	0.1	M/I A/M L N/A	Y				
	Int Stops	0.0	M/I A/M L N/A	Y				
1	Win Int Sash	.	M/I A/M L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	A/M L N/A	Y				
C	Win Casing	.	A/M L N/A	Y				
D	Header Stop	.	M/I A/M L N/A	Y				
	Int Stops	.	M/I A/M L N/A	Y				
1	Win Int Sash		M/I A/M L N/A	Y				
2	Exterior Sill		M/I SF L N/A	Y				
3	Part Bead		M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B	Up Cab Frame	0.1	A/M L N/A	Y				
C D	Up Cab Door	0.0	A/M L N/A	Y				
	Up Cab Walls	0.2	A/M L N/A	Y				
1 2	Up Cab Shlvs	0.1	A/M L N/A	Y				
3 4	Supports	0.2	A/M L N/A	Y				
	Low Cab Fram	0.2	A/M L N/A	Y				
A B	Low Cab Door	-0.4	A/M L N/A	Y				
C D	Low Cab Walls	0.2	A/M L N/A	Y				
	Low Cab Shlvs	0.0	A/M L N/A	Y				
1 2	Supports	0.1	A/M L N/A	Y				
3 4	Drawers	0.0	A/M L N/A	Y				
A B C D	Win Above 5'	/	M/I A/M L N/A	Y				
D2	door	0.1	M/I A/M L N/A	Y				
	CASing	0.0	M/I A/M L N/A	Y				
	jamb	0.2	M/I A/M L N/A	Y				
	thresh	0.0	M/I A/M L N/A	Y				
	(marble)		M/I A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield — Inspector (print)
M-1950 — Lic #
Christine Caulfield — Signature
02/22/10 — Date

Risk Assessor (print) — Signature — Date

Address of Property: 275 Mechanic St. Apt. # ——— City: Marlborough

Bathroom #1

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.0	A/M L N/A	Y				
A B C D	Low Walls	0.1	A/M L N/A	Y				
A B C D	Baseboards	0.0	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
A B (C) D	Radiator	0.5	A/M L N/A	Y				
	Floor 0.4	tile	A/M L N/A	Y				
	Ceiling	DC	A/M L N/A	Y				
A (B)	Door	0.0	A/M L N/A	Y				
C D	Door Casing	0.0	A/M L N/A	Y				
(1) 2	Door Jamb	0.1	A/M L N/A	Y				
3 4	Threshold	0.0	A/M L N/A	Y				
A B	Door	.	A/M L N/A	Y				
C D	Door Casing	.	A/M L N/A	Y				
1 2	Door Jamb	.	A/M L N/A	Y				
3 4	Threshold	.	A/M L N/A	Y				
A	Closet Door	.	A/M L N/A	Y				
B	Cl Casing	.	A/M L N/A	Y				
C	Closet Jamb	.	A/M L N/A	Y				
D	Closet Walls	.	A/M L N/A	Y				
	Cl Baseboard	.	A/M L N/A	Y				
1	Closet Pole	.	A/M L N/A	Y				
2	Closet Shelf	.	A/M L N/A	Y				
3	Cl Supports	.	A/M L N/A	Y				
4	Closet Floor	.	A/M L N/A	Y				
	Closet Ceiling	.	A/M L N/A	Y				
A (B)	Up Cab Frame	.	A/M L N/A	Y				
C D	Up Cab Door	.	A/M L N/A	Y				
	Up Cab Walls	.	A/M L N/A	Y				
(1) 2	Up Cab Shlvs	0.0	A/M L N/A	Y				
3 4	Supports	0.0	A/M L N/A	Y				
		.	M/I A/M L N/A	Y				
		.	M/I A/M L N/A	Y				
		.	M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A (B)	Up Cab Frame	0.1	A/M L N/A	Y				
C D	Up Cab Door	0.0	A/M L N/A	Y				
	Up Cab Walls	0.2	A/M L N/A	Y				
(1) 2	Up Cab Shlvs	0.1	A/M L N/A	Y				
3 4	Supports	0.0	A/M L N/A	Y				
A (B)	Up Cab Frame	0.1	A/M L N/A	Y	free			
C D	Up Cab Door	0.0	A/M L N/A	Y	standing			
	Up Cab Walls	0.2	A/M L N/A	Y	cabinet			
(1) 2	Up Cab Shlvs	0.1	A/M L N/A	Y				
3 4	Supports	0.1	A/M L N/A	Y				
	Low Cab Fram	.	A/M L N/A	Y				
A B	Low Cab Door	.	A/M L N/A	Y				
C D	Low Cab Walls	.	A/M L N/A	Y				
	Low Cab Shlvs	.	A/M L N/A	Y				
1 2	Supports	.	A/M L N/A	Y				
3 4	Drawers	.	A/M L N/A	Y				
	Low Cab Fram	.	A/M L N/A	Y				
A B	Low Cab Door	.	A/M L N/A	Y				
C D	Low Cab Walls	.	A/M L N/A	Y				
	Low Cab Shlvs	.	A/M L N/A	Y				
1 2	Supports	.	A/M L N/A	Y				
3 4	Drawers	.	A/M L N/A	Y				
	Low Cab Fram	.	A/M L N/A	Y				
A B	Low Cab Door	.	A/M L N/A	Y				
C D	Low Cab Walls	.	A/M L N/A	Y				
	Low Cab Shlvs	.	A/M L N/A	Y				
1 2	Supports	.	A/M L N/A	Y				
3 4	Drawers	.	A/M L N/A	Y				
A	Window Sill	0.2	M/I A/M L N/A	Y				
(B)	Win Apron	0.1	A/M L N/A	Y				
(C)	Win Casing	0.0	A/M L N/A	Y				
D	Header Stop	0.1	M/I A/M L N/A	Y				
	Int Stops	0.2	M/I A/M L N/A	Y				
1	Win Int Sash	0.3	M/I A/M L N/A	Y				
2	Exterior Sill	0.0	M/I SF L N/A	Y				
(3)	Pan Bead	0.1	M/I L N/A	Y				
4	Blind Stop	0.0	M/I SF L N/A	Y				
	Win Ext Sash	0.2	M/I L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield	M-1950	Christine Caulfield	02/22/10
Inspector (print)	Lic #	Signature	Date

Risk Assessor (print) Lic # Signature Date

Address of Property: 275 Mechanic St. Apt. # —— City: Marlborough

HALLWAY: Interior # 1 or Common Hallway: Front Rear Floor #____

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.1	A/M L N/A	Y				
A B C D	Low Walls	0.0	A/M L N/A	Y				
A B C D	Baseboards	0.5	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
A B C D	Radiator	/	A/M L N/A	Y				
	Floor	tile	A/M L N/A	Y				
	Ceiling	0.1	A/M L N/A	Y				
A B	Door	0.0	A/M L N/A	Y				
C D	Door Casing	0.2	A/M L N/A	Y				
1 2	Door Jamb	0.1	A/M L N/A	Y				
3 4	Threshold	0.1	A/M L N/A	Y				
A B	Door Room 2	/	A/M L N/A	Y				
C D	Door Casing	0.0	A/M L N/A	Y				
1 2	Door Jamb	0.2	A/M L N/A	Y				
3 4	Threshold	0.1	A/M L N/A	Y				
A B	Door to cellar	0.0	A/M L N/A	Y				
C D	Door Casing	0.1	A/M L N/A	Y				
1 2	Door Jamb	1.5	A/M L N/A	Y				
3 4	Threshold	0.1	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	0.0	A/M L N/A	Y				
1 2	Door Jamb	0.0	A/M L N/A	Y				
3 4	Threshold	carpet	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	0.0	A/M L N/A	Y				
# 1	Door Jamb	0.2	A/M L N/A	Y				
	Threshold	tile	A/M L N/A	Y				
A	Closet Door	.	A/M L N/A	Y				
B	CI Casing		A/M L N/A	Y				
C	Closet Jamb	.	A/M L N/A	Y				
D	Closet Walls	.	A/M L N/A	Y				
	CI Baseboard	.	A/M L N/A	Y				
1	Closet Pole	.	A/M L N/A	Y				
2	Closet Shelf	.	A/M L N/A	Y				
3	CI Supports	.	A/M L N/A	Y				
4	Closet Floor	.	A/M L N/A	Y				
	Closet Ceiling	/	A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Closet Door	/	A/M L N/A	Y				
B	CI Casing		A/M L N/A	Y				
C	Closet Jamb		A/M L N/A	Y				
D	Closet Walls		A/M L N/A	Y				
	CI Baseboard		A/M L N/A	Y				
1	Closet Pole	.	A/M L N/A	Y				
2	Closet Shelf	.	A/M L N/A	Y				
3	CI Supports	.	A/M L N/A	Y				
4	Closet Floor	.	A/M L N/A	Y				
	Closet Ceiling	.	A/M L N/A	Y				
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.1	A/M L N/A	Y				
C	Win Casing	0.2	A/M L N/A	Y				
D	Header Stop	0.2	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
1	Win Int Sash	/	M/I A/M L N/A	Y	opening to			
2	Exterior Sill	/	M/I SF L N/A	Y		Room 5		
3	Part Bead	/	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	/	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron		A/M L N/A	Y				
C	Win Casing	.	A/M L N/A	Y				
D	Header Stop	.	M/I A/M L N/A	Y				
	Int Stops	.	M/I A/M L N/A	Y				
1	Win Int Sash	.	M/I A/M L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B C D	Win Above 5'	INT	M/I A/M L N/A	Y	Skylight			
A B C D	Ceiling Molding	/	M/I A/M L N/A	Y				
		.	M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:
ACD baseboards: 0.0
D radiator 0.5
D2 casing 0.0 D2 jamb 0.1

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield — M-1950 — Christine Caulfield — 02/22/10
Inspector (print) — Lic # — Signature — Date

Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 275 Mechanic St. Apt. # — City: Marlborough

HALLWAY: Interior # 2 or Common Hallway: Front Rear Floor #

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.2	A/M L N/A	Y				
A B C D	Low Walls	0.3	A/M L N/A	Y				
A B C D	Baseboards	1.5	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
A B C D	Radiator	/	A/M L N/A	Y				
	Floor	CW	A/M L N/A	Y				
	Ceiling	0.2	A/M L N/A	Y				
A B	Door double	0.0	A/M L N/A	Y				
C D	Door Casing	0.1	A/M L N/A	Y				
1 2	Door Jamb	0.0	A/M L N/A	Y				
3 4	Threshold	0.1	A/M L N/A	Y				
A B	Door	0.0	A/M L N/A	Y				
C D	Door Casing	0.1	A/M L N/A	Y				
1 2	Door Jamb	0.0	A/M L N/A	Y				
3 4	Threshold	CW	A/M L N/A	Y				
A B	Door	0.3	A/M L N/A	Y				
C D	Door Casing	0.1	A/M L N/A	Y				
1 2	Door Jamb	0.0	A/M L N/A	Y				
3 4	Threshold	CW	A/M L N/A	Y				
A B	Door	0.4	A/M L N/A	Y				
C D	Door Casing	0.1	A/M L N/A	Y				
1 2	Door Jamb	0.0	A/M L N/A	Y				
3 4	Threshold	CW	A/M L N/A	Y				
A B	Door	.	A/M L N/A	Y				
C D	Door Casing	.	A/M L N/A	Y				
#	Door Jamb	.	A/M L N/A	Y				
	Threshold	.	A/M L N/A	Y				
A	Closet Door	0.0	A/M L N/A	Y				
B	Cl Casing	0.3	A/M L N/A	Y				
C	Closet Jamb	0.2	A/M L N/A	Y				
D	Closet Walls	0.2	A/M L N/A	Y				
	Cl Baseboard	9.9	A/M L N/A	Y				
1	Closet Pole	/	A/M L N/A	Y				
2	Closet Shelf	/	A/M L N/A	Y				
3	Cl Supports	9.4	A/M L N/A	Y				
4	Closet Floor	CW	A/M L N/A	Y				
	Closet Ceiling	0.1	A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Closet Door	.	A/M L N/A	Y				
B	Cl Casing	.	A/M L N/A	Y				
C	Closet Jamb	.	A/M L N/A	Y				
D	Closet Walls	.	A/M L N/A	Y				
	Cl Baseboard	.	A/M L N/A	Y				
1	Closet Pole	.	A/M L N/A	Y				
2	Closet Shelf	.	A/M L N/A	Y				
3	Cl Supports	.	A/M L N/A	Y				
4	Closet Floor	.	A/M L N/A	Y				
	Closet Ceiling	.	A/M L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	A/M L N/A	Y				
C	Win Casing	.	A/M L N/A	Y				
D	Header Stop	.	M/I A/M L N/A	Y				
	Int Stops	.	M/I A/M L N/A	Y				
1	Win Int Sash	.	M/I A/M L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A	Window Sill	.	M/I A/M L N/A	Y				
B	Win Apron	.	A/M L N/A	Y				
C	Win Casing	.	A/M L N/A	Y				
D	Header Stop	.	M/I A/M L N/A	Y				
	Int Stops	.	M/I A/M L N/A	Y				
1	Win Int Sash	.	M/I A/M L N/A	Y				
2	Exterior Sill	.	M/I SF L N/A	Y				
3	Part Bead	.	M/I L N/A	Y				
4	Blind Stop	.	M/I SF L N/A	Y				
	Win Ext Sash	.	M/I L N/A	Y				
A B C D	Win Above 5'	.	M/I A/M L N/A	Y				
A B C D	Ceiling Molding	.	M/I A/M L N/A	Y				
		.	M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield — Inspector (print)
M-1950 — Lic #
Christine Caulfield — Signature
02/22/10 — Date

Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 275 Mechanic St. Apt. # — City: Marlborough

STAIRCASE 1st floor to basement

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	1.8	A/M (L) N/A	(Y)				
A B C D	Low Walls	1.9	(A/M) (L) N/A	(Y)				
A B C D	Baseboards	/	A/M L N/A	Y				
A B C D	Chair Rail	9.0	(A/M) (L) N/A	(Y)				
A B C D	Radiator	/	A/M L N/A	Y				
	Floor	0.7	A/M L N/A	Y	Landing			
	Ceiling	1.9	(A/M) (L) N/A	(Y)				
A B	Door	0.0	A/M L N/A	Y				
C D	Door Casing	1.5	(A/M) (L) N/A	(Y)				
(1) 2	Door Jamb	2.9	(A/M) (L) N/A	(Y)				
3 4	Threshold	0.8	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
#	Door Jamb	/	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
A	Closet Door	/	A/M L N/A	Y				
B	Cl Casing	/	A/M L N/A	Y				
C	Closet Jamb	/	A/M L N/A	Y				
D	Closet Walls	/	A/M L N/A	Y				
	Cl Baseboard	/	A/M L N/A	Y				
1	Closet Pole	/	A/M L N/A	Y				
2	Closet Shelf	/	A/M L N/A	Y				
3	Cl Supports	/	A/M L N/A	Y				
4	Closet Floor	/	A/M L N/A	Y				
	Closet Ceiling	/	A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	9.9	M/I (A/M) (L) N/A	(Y)	STAINED GLASS			
(B)	Win Apron	9.2	(A/M) (L) N/A	(Y)				
C	Win Casing	9.0	(A/M) (L) N/A	(Y)				
D	Header Stop	8.5	M/I A/M (L) N/A	(Y)				
	Int Stops	9.2	M/I (A/M) (L) N/A	(Y)				
(1)	Win Int Sash	9.9	M/I (A/M) (L) N/A	(Y)				
2	Exterior Sill	fixed	M/I SF L N/A	Y				
3	Part Bead	fixed	M/I L N/A	Y				
4	Blind Stop	fixed	M/I SF L N/A	Y				
	Win Ext Sash	9.3	M/I L N/A	Y				
A	Window Sill	/	M/I A/M L N/A	Y				
B	Win Apron		A/M L N/A	Y				
C	Win Casing		A/M L N/A	Y				
D	Header Stop	/	M/I A/M L N/A	Y				
	Int Stops	/	M/I A/M L N/A	Y				
1	Win Int Sash	/	M/I A/M L N/A	Y				
2	Exterior Sill	/	M/I SF L N/A	Y				
3	Part Bead	/	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	/	M/I L N/A	Y				
	~~Newel Post~~	9.5	(A/M) (L) N/A	(Y)				
	~~Railing Cap~~	/	A/M L N/A	Y				
	Handrail	/	A/M L N/A	Y				
	Balusters	9.3	(A/M) (L) N/A	(Y)				
	Lower rail	/	A/M L N/A	Y				
	Treads	0.6	A/M L N/A	Y				
	Risers	5.7	(A/M) (L) N/A	(Y)				
	Stringer	8.0	(A/M) (L) N/A	(Y)				
	Floor Edge	9.9	(A/M) (L) N/A	(Y)				
	Floor Casing	9.9	(A/M) (L) N/A	(Y)				
A	coat rack	1.5	M/I (A/M) (L) N/A	(Y)				

COMMENTS / STRUCTURAL DEFECTS:
all boards/ shelves/ supports/ brick/stone
test positive - all 8.0 to 9.9 mg/cm2
(A/M) (L) (Y)

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield	M-1950	Christine Caulfield	02/22/10
Inspector (print)	Lic #	Signature	Date

Risk Assessor (print)	Lic #	Signature	Date

Address of Property: 275 Mechanic St. Apt. # — City: Marlborough

STAIRCASE 1st to 2nd Floor

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.2	A/M L N/A	Y				
A B C D	Low Walls	0.1	A/M L N/A	Y				
A B C D	Baseboards	1.1	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
A B C D	Radiator	/	A/M L N/A	Y				
	Floor	CoV	A/M L N/A	Y				
	Ceiling	0.1	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
#	Door Jamb	/	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
A	Closet Door	/	A/M L N/A	Y				
B	Cl Casing	/	A/M L N/A	Y				
C	Closet Jamb	/	A/M L N/A	Y				
D	Closet Walls	/	A/M L N/A	Y				
	Cl Baseboard	/	A/M L N/A	Y				
1	Closet Pole	/	A/M L N/A	Y				
2	Closet Shelf	/	A/M L N/A	Y				
3	Cl Supports	/	A/M L N/A	Y				
4	Closet Floor	/	A/M L N/A	Y				
	Closet Ceiling	/	A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill	0.1	M/I A/M L N/A	Y				
B	Win Apron	0.0	A/M L N/A	Y				
C	Win Casing	0.2	A/M L N/A	Y				
D	Header Stop	0.1	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I SF L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				
A	Window Sill	/	M/I A/M L N/A	Y				
B	Win Apron	/	A/M L N/A	Y				
C	Win Casing	/	A/M L N/A	Y				
D	Header Stop	/	M/I A/M L N/A	Y				
	Int Stops	/	M/I A/M L N/A	Y				
1	Win Int Sash	/	M/I A/M L N/A	Y				
2	Exterior Sill	/	M/I SF L N/A	Y				
3	Part Bead	/	M/I L N/A	Y				
4	Blind Stop	/	M/I SF L N/A	Y				
	Win Ext Sash	/	M/I L N/A	Y				
	Newel Post	0.1	A/M L N/A	Y				
	Railing Cap	0.0	A/M L N/A	Y				
	Handrail	0.2	A/M L N/A	Y				
	Balusters	0.1	A/M L N/A	Y				
	Lower rail	0.1	A/M L N/A	Y				
	Treads	CoV	A/M L N/A	Y				
	Risers	CoV	A/M L N/A	Y				
	Stringer	1.1	A/M L N/A	Y				
	Floor Edge	N.C	A/M L N/A	Y				
	Floor Casing	N.C	A/M L N/A	Y				
		/	M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield — M-1950 — Christine Caulfield — 02/22/10
Inspector (print) — Lic # — Signature — Date

Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 275 Mechanic St. Apt. # — City: Marlborough

BASEMENT/LAUNDRY AREA

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Walls	0.0	A/M L N/A	Y				
A B C D	Walls	0.2	A/M L N/A	Y				
A B C D	Walls	0.0	A/M L N/A	Y				
A B C D	Walls	0.1	A/M L N/A	Y				
A B C D	Baseboards	/	A/M L N/A	Y				
A B C D	Chair rails	/	A/M L N/A	Y				
	Floor	0.2	A/M L N/A	Y				
	Ceiling	0.7	A/M L N/A	Y				
A B C D	Chimney	0.0	A/M L N/A	Y				
A B C D	Support Colum	0.4	A/M L N/A	Y				
A B	Door	4.8	A/M L N/A	Y				
C D	Door Casing	4.9	A/M L N/A	Y				
1 2	Door Jamb	5.7	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B	Door	/	A/M L N/A	Y				
C D	Door Casing	/	A/M L N/A	Y				
1 2	Door Jamb	/	A/M L N/A	Y				
3 4	Threshold	/	A/M L N/A	Y				
A B C D	Cabinets	/	A/M L N/A	Y				
A B	Benches	/	A/M L N/A	Y				
C D	Supports	/	A/M L N/A	Y				
A	Closet Door	/	A/M L N/A	Y				
B	Cl Casing	/	A/M L N/A	Y				
C	Closet Jamb	/	A/M L N/A	Y				
D	Closet Walls	/	A/M L N/A	Y				
	Cl Baseboard	/	A/M L N/A	Y				
1	Closet Pole	/	A/M L N/A	Y				
2	Closet Shelf	/	A/M L N/A	Y				
3	Cl Supports	/	A/M L N/A	Y				
4	Closet Floor	/	A/M L N/A	Y				
	Closet Ceiling	/	A/M L N/A	Y				

Comments/Structural Defects

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Pipes	/	A/M L N/A	Y				
A B C D	Sink	/	A/M L N/A	Y				
A B C D	Drainpipe	/	A/M L N/A	Y				
A B C D	Serviceboard	0.0	A/M L N/A	Y				
A B	Shelves	/	A/M L N/A	Y				
C D	Supports	/	A/M L N/A	Y				
A B	Shelves	/	A/M L N/A	Y				
C D	Supports	/	A/M L N/A	Y				
A B	Shelves	/	A/M L N/A	Y				
C D	Supports	/	A/M L N/A	Y				
	Window frame	/	M/I A/M L N/A	Y				
A B	Window Sash	/	M/I A/M L N/A	Y				
C D	Exterior Sill	1.5	M/I A/M L N/A	Y				
1 2	Part Bead	/	M/I A/M L N/A	Y				
3 4	Win Ext Sash	/	M/I A/M L N/A	Y				
	Window frame	1.6	M/I A/M L N/A	Y				
A B	Window Sash	1.0	M/I A/M L N/A	Y				
C D	Exterior Sill	1.1	M/I A/M L N/A	Y				
1 2	Part Bead	1.2	M/I A/M L N/A	Y				
3 4	Win Ext Sash	1.1	M/I A/M L N/A	Y				
	Window frame	/	M/I A/M L N/A	Y				
A B	Window Sash	/	M/I A/M L N/A	Y				
C D	Exterior Sill	/	M/I A/M L N/A	Y				
1 2	Part Bead	/	M/I A/M L N/A	Y				
3 4	Win Ext Sash	/	M/I A/M L N/A	Y				
	Window frame	/	M/I A/M L N/A	Y				
A B	Window Sash	/	M/I A/M L N/A	Y				
C D	Exterior Sill	/	M/I A/M L N/A	Y				
1 2	Part Bead	/	M/I A/M L N/A	Y				
3 4	Win Ext Sash	/	M/I A/M L N/A	Y				
	Newel Posts	/	A/M L N/A	Y				
A B	Handrail	/	A/M L N/A	Y				
C D	Balusters	/	A/M L N/A	Y				
1 2	Lower rail	/	A/M L N/A	Y				
3 4	Treads	/	A/M L N/A	Y				
	Risers	/	A/M L N/A	Y				
	Stringer	/	A/M L N/A	Y				
A B C D	Oil Tank	/	L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield — M-1950 — Christine Caulfield — 02/22/10

Inspector (print) — Lic # — Signature — Date

Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 275 Mechanic St. Apt. # — City: Marlborough

PORCH (A) B C D (circle one) (1st fl) 2nd fl 3rd fl 4th fl (circle one)

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B	Siding	0.2	L N/A	Y				
C D	Corner Boards	/	L N/A	Y				
	Upper Trim	0.5	L N/A	Y				
	Ceiling	0.2	L N/A	Y				
	Joists	0.5	L N/A	Y				
A	Door	0.1	A/M L N/A	Y				
B	Storm Door	/	A/M L N/A	Y				
(C)	Door Casing	CW	A/M L N/A	Y				
D	Door Jamb	0.1	A/M L N/A	Y				
(1) 2	Threshold	0.0	A/M L N/A	Y				
3 4	Kickplate	CW	A/M L N/A	Y				
A	Door	0.1	A/M L N/A	Y				
B	Storm Door	/	A/M L N/A	Y				
C	Door Casing	CW	A/M L N/A	Y				
(D)	Door Jamb	0.2	A/M L N/A	Y				
(1) 2	Threshold	Met	A/M L N/A	Y				
3 4	Kickplate	CW	A/M L N/A	Y				
A (B)	Window Sill	CW	A/M L N/A	Y				
C D	Win Casing	CW	A/M L N/A	Y				
(1) 2	Window Sash	VR	A/M L N/A	Y				
3 4	Mullions	/	A/M L N/A	Y				
A B	Window Sill	0.1	A/M L N/A	Y				
(C) D	Win Casing	0.2	A/M L N/A	Y				
(1) 2	Window Sash	V.R	A/M L N/A	Y				
3 4	Mullions	/	A/M L N/A	Y				
A B	Window Sill	/	A/M L N/A	Y				
C D	Win Casing	/	A/M L N/A	Y				
1 2	Window Sash	/	A/M L N/A	Y				
3 4	Mullions	/	A/M L N/A	Y				
A B	Window Sill	/	A/M L N/A	Y				
C D	Win Casing	/	A/M L N/A	Y				
1 2	Window Sash	/	A/M L N/A	Y				
3 4	Mullions	/	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Support Clmns	0.1	A/M L N/A	Y				
	Newel post	0.2	A/M L N/A	Y				
	Railing Cap	0.1	A/M L N/A	Y				
	Handrail	0.2	A/M L N/A	Y				
	Balusters	0.1	A/M L N/A	Y				
	Lower Rail	0.2	A/M L N/A	Y				
	Treads	0.0	A/M L N/A	Y				
	Risers	0.0	A/M L N/A	Y				
	Stringer	0.0	A/M L N/A	Y				
	Lower Walls	0.1	A/M L N/A	Y				
	Lattice plastic	0.0	A/M L N/A	Y				
	Lower Trim	0.0	A/M L N/A	Y				
	Floor	0.1	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield — M-1950 — Christine Caulfield — 02/22/10
Inspector (print) — Lic # — Signature — Date

Risk Assessor (print) — Lic # — Signature — Date

Address of Property: 275 Mechanic St. Apt. # ——— City: Marlborough

PORCH A B C (D) (circle one) (1st fl) 2nd fl 3rd fl 4th fl (circle one) PORCH #2

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B	Siding	0.0	L N/A	Y				
C D	Corner Boards	/	L N/A	Y				
	Upper Trim	5.6	(L) N/A	(Y)				
	Ceiling	/	L N/A	Y				
	Joists	/	L N/A	Y				
A	Door	.	A/M L N/A	Y				
B	Storm Door	.	A/M L N/A	Y				
C	Door Casing	.	A/M L N/A	Y				
D	Door Jamb	.	A/M L N/A	Y				
1 2	Threshold	.	A/M L N/A	Y				
3 4	Kickplate	.	A/M L N/A	Y				
A	Door Slider	0.1	A/M L N/A	Y				
(B)	Storm Door	/	A/M L N/A	Y				
C	Door Casing	0.0	A/M L N/A	Y				
D	Door Jamb	0.2	A/M L N/A	Y				
1 2	Threshold	Met	A/M L N/A	Y				
3 4	Kickplate	NC	A/M L N/A	Y				
(A) B	Window Sill	0.2	A/M L N/A	Y				
C D	Win Casing	0.4	A/M L N/A	Y				
(1) 2	Window Sash	0.4	A/M L N/A	Y				
3 4	Mullions	/	A/M L N/A	Y				
A B	Window Sill	.	A/M L N/A	Y				
C D	Win Casing	.	A/M L N/A	Y				
1 2	Window Sash	.	A/M L N/A	Y				
3 4	Mullions	.	A/M L N/A	Y				
A B	Window Sill	.	A/M L N/A	Y				
C D	Win Casing	.	A/M L N/A	Y				
1 2	Window Sash	.	A/M L N/A	Y				
3 4	Mullions	.	A/M L N/A	Y				
A B	Window Sill	.	A/M L N/A	Y				
C D	Win Casing	.	A/M L N/A	Y				
1 2	Window Sash	.	A/M L N/A	Y				
3 4	Mullions	.	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Support Clmns	/	A/M L N/A	Y				
	Newel post	NC	A/M L N/A	Y				
	Railing Cap	N.C	A/M L N/A	Y				
	Handrail	N.C	A/M L N/A	Y				
	Balusters	N.C	A/M L N/A	Y				
	Lower Rail	N.C	A/M L N/A	Y				
	Treads	0.0	A/M L N/A	Y				
	Risers	0.1	A/M L N/A	Y				
	Stringer	0.1	A/M L N/A	Y				
	Lower Walls	NC	A/M L N/A	Y				
	Lattice	/	A/M L N/A	Y				
	Lower Trim	N.C	A/M L N/A	Y				
	Floor	NC	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				
		.	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Christine Caulfield	M-1950	Christine Caulfield	02/22/10
Inspector (print)	Lic #	Signature	Date

Risk Assessor (print) Lic# Signature Date

Address of Property: 275 Mechanic St. Apt. # —— City: Marlborough

EXTERIOR A Side

SIDE A	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Siding	0.0	L N/A	Y				
	Corner Boards	/	L N/A	Y				
	Lower Trim	/	L N/A	Y				
	Upper Trim	8.9	(L) N/A	(Y)	above right window			
	Win Above 5'	VR + COIL	L N/A	Y				
	Porch Above 5'	/	L N/A	Y				
(A) 1 2 3 4	Storm Door	.	A/M L N/A	Y				
	Door	please	A/M L N/A	Y				
	Door Casing	See	A/M L N/A	Y				
	Door Jamb	porch	A/M L N/A	Y				
	Threshold	page	A/M L N/A	Y				
	Kickplate	.	A/M L N/A	Y				
A 1 2 3 4	Storm Door	.	A/M L N/A	Y				
	Door	.	A/M L N/A	Y				
	Door Casing	.	A/M L N/A	Y				
	Door Jamb	.	A/M L N/A	Y				
	Threshold	.	A/M L N/A	Y				
	Kickplate	.	A/M L N/A	Y				
A 1 2 3 4	Door		A/M L N/A	Y				
	Door Casing	.	A/M L N/A	Y				
	Door Jamb	.	A/M L N/A	Y				
	Threshold	.	A/M L N/A	Y				
A #1	Window Sill	CW	A/M L N/A	Y				
	Win Casing	CW	A/M L N/A	Y				
	Window Sash	VR	A/M L N/A	Y				
A #2	Window Sill	CW	A/M L N/A	Y				
	Win Casing	CW	A/M L N/A	Y				
	Window Sash	VR	A/M L N/A	Y				
A #3	Window Sill	CW	A/M L N/A	Y				
	Win Casing	CW	A/M L N/A	Y				
	Window Sash	VR	A/M L N/A	Y				
A	Lamp Post	/	L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

- shingles above right picture window 8.2 (L) (Y)
- small door + frame behind left bushes 1.1 to 1.2 (A/M) (L) (Y)

SIDE A	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A #	Window Sill	.	A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Window Sash	.	A/M L N/A	Y				
A #	Cellar Win Sill	.	A/M L N/A	Y				
	Cel Win Sash		A/M L N/A	Y				
	Cel Win Frame	.	A/M L N/A	Y				
	Screen Frame	.	A/M L N/A	Y				
A #	Cellar Win Sill	.	A/M L N/A	Y				
	Cel Win Sash		A/M L N/A	Y				
	Cel Win Frame	.	A/M L N/A	Y				
	Screen Frame	.	A/M L N/A	Y				
A #	Cellar Win Sill	.	A/M L N/A	Y				
	Cel Win Sash	.	A/M L N/A	Y				
	Cel Win Frame	.	A/M L N/A	Y				
	Screen Frame	.	A/M L N/A	Y				
A #	Cellar Win Sill	.	A/M L N/A	Y				
	Cel Win Sash	.	A/M L N/A	Y				
	Cel Win Frame	.	A/M L N/A	Y				
	Screen Frame	.	A/M L N/A	Y				
A	Foundation	0.4	L N/A	Y				
	Bulkhead	.	A/M L N/A	Y				
	Fences		A/M L N/A	Y				
	Shutters		A/M L N/A	Y				
A	Newel post		A/M L N/A	Y				
	Railing Cap		A/M L N/A	Y				
	Handrail		A/M L N/A	Y				
	Balusters		A/M L N/A	Y				
	Lower Rail		A/M L N/A	Y				
	Treads		A/M L N/A	Y				
	Risers		A/M L N/A	Y				
	Stringer		A/M L N/A	Y				
	Lattice	.	A/M L N/A	Y				
A	Drain Pipes	.	L N/A	Y				
	Elec Conduit		L N/A	Y				
	Oil Fill Pipe	.	L N/A	Y				
	Overhang Trim	.	A/M L N/A	Y				

Excluded Surfaces: Surfaces listed in this box can be made intact only by a licensed deleader

SIDE A	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	IC DATE	IC METH
A				
A				
A				
A				

Soil Test Results

(Must be less than 400 ppm for play area / 1200 ppm for bare soil)

LOCATION	AREA MEASUREMENT (Square Feet)	RESULT (PPM)	REMED DATE	REMED METH
Play Area				
Bare soil				

Comments:

Christine Caulfield	M-1950	Christine Caulfield	02/22/10
Inspector (print)	Lic #	Signature	Date

Risk Assessor (print)	Lic#	Signature	Date

Address of Property: 275 Mechanic St. Apt. # —— City: Marlborough

EXTERIOR B Side

SIDE B	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
B	Siding Lower	0.0	L N/A	Y				
	Corner Boards	/	L N/A	Y				
	Lower Trim	/	L N/A	Y				
	Upper Trim	5.8	(L) N/A	(Y)				
	Win Above 5'	VR	+ coil L N/A	Y				
	Porch Above 5'	/	L N/A	Y				
B 1 2 3 4	Storm Door	/	A/M L N/A	Y				
	Door	/	A/M L N/A	Y				
	Door Casing	/	A/M L N/A	Y				
	Door Jamb	/	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
	Kickplate	/	A/M L N/A	Y				
B 1 2 3 4	Storm Door	/	A/M L N/A	Y				
	Door	/	A/M L N/A	Y				
	Door Casing	/	A/M L N/A	Y				
	Door Jamb	/	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
	Kickplate	/	A/M L N/A	Y				
B 1 2 3 4	Door	/	A/M L N/A	Y				
	Door Casing	/	A/M L N/A	Y				
	Door Jamb	/	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
B # 1	Window Sill	CW	A/M L N/A	Y	STRINGS GLASS			
	Win Casing	CW	A/M L N/A	Y	window			
	Window Sash	2.9	A/M (L) N/A	(Y)				
B #	Window Sill	/	A/M L N/A	Y				
	Win Casing	/	A/M L N/A	Y				
	Window Sash	/	A/M L N/A	Y				
B #	Window Sill	/	A/M L N/A	Y				
	Win Casing	/	A/M L N/A	Y				
	Window Sash	/	A/M L N/A	Y				
B	Lamp Post	/	L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

* Side B shingles above 2nd floor windows test 5.6 (L) (Y)

SIDE B	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
B #	Window Sill	/	A/M L N/A	Y				
	Win Casing	/	A/M L N/A	Y				
	Window Sash	/	A/M L N/A	Y				
B #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	A/M L N/A	Y				
	Cel Win Frame	/	A/M L N/A	Y				
	Screen Frame	/	A/M L N/A	Y				
B #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	A/M L N/A	Y				
	Cel Win Frame	/	A/M L N/A	Y				
	Screen Frame	/	A/M L N/A	Y				
B #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	A/M L N/A	Y				
	Cel Win Frame	/	A/M L N/A	Y				
	Screen Frame	/	A/M L N/A	Y				
B #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	A/M L N/A	Y				
	Cel Win Frame	/	A/M L N/A	Y				
	Screen Frame	/	A/M L N/A	Y				
B	Foundation	0.1	L N/A	Y				
	Bulkhead	/	A/M L N/A	Y				
	Fences	0.0	A/M L N/A	Y				
	Shutters	/	A/M L N/A	Y				
B	Newel post	/	A/M L N/A	Y				
	Railing Cap	/	A/M L N/A	Y				
	Handrail	/	A/M L N/A	Y				
	Balusters	/	A/M L N/A	Y				
	Lower Rail	/	A/M L N/A	Y				
	Treads	/	A/M L N/A	Y				
	Risers	/	A/M L N/A	Y				
	Stringer	/	A/M L N/A	Y				
	Lattice	/	A/M L N/A	Y				
B	Drain Pipes	0.0	L N/A	Y				
	Elec Conduit	/	L N/A	Y				
	Oil Fill Pipe	/	L N/A	Y				
	Overhang Trim	/	A/M L N/A	Y				

Excluded Surfaces: Surfaces listed in this box can be made intact only by a licensed deleader

SIDE A	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	IC DATE	IC METH
A				
A				
A				
A				

Soil Test Results

(Must be less than 400 ppm for play area / 1200 ppm for bare soil)

LOCATION	AREA MEASUREMENT (Square Feet)	RESULT (PPM)	REMED DATE	REMED METH
Play Area				
Bare soil				

Comments:

Christine Caulfield | **M-1950** | Christine Caulfield | 02/22/10
Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic# | Signature | Date

Address of Property: 275 Mechanic St. Apt. # ——— City: Marlborough

EXTERIOR C Side

SIDE C	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
C	Siding	0.0	L N/A	Y				
	Corner Boards	/	L N/A	Y				
	Lower Trim	/	L N/A	Y				
	Upper Trim	5.8	(L) N/A	(Y)				
	Win Above 5'	VR	+ coil L N/A	Y				
	Porch Above 5'	/	L N/A	Y				
(C) 1 2 3 4	Storm Door	/	A/M L N/A	Y	TO ROOM LY			
	Door	0.0	A/M L N/A	Y				
	Door Casing	0.0	A/M L N/A	Y				
	Door Jamb	0.2	A/M L N/A	Y				
	Threshold	0.0	A/M L N/A	Y				
	Kickplate	0.1	A/M L N/A	Y				
C 1 2 3 4	Storm Door	.	A/M L N/A	Y				
	Door	.	A/M L N/A	Y				
	Door Casing	.	A/M L N/A	Y				
	Door Jamb	.	A/M L N/A	Y				
	Threshold	.	A/M L N/A	Y				
	Kickplate	.	A/M L N/A	Y				
C 1 2 3 4	Door	.	A/M L N/A	Y				
	Door Casing	.	A/M L N/A	Y				
	Door Jamb	.	A/M L N/A	Y				
	Threshold	.	A/M L N/A	Y				
C # 1	Window Sill	0.0	A/M L N/A	Y	above bulkhead			
	Win Casing	0.1	A/M L N/A	Y				
	Window Sash	VR	A/M L N/A	Y				
C #	Window Sill	.	A/M L N/A	Y				
	Win Casing	.	A/M L N/A	Y				
	Window Sash	.	A/M L N/A	Y				
C #	Window Sill	.	A/M L N/A	Y				
	Win Casing	.	A/M L N/A	Y				
	Window Sash	.	A/M L N/A	Y				
C	Lamp Post	.	L N/A	Y				

SIDE C	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
C #	Window Sill	.	A/M L N/A	Y				
	Win Casing	.	A/M L N/A	Y				
	Window Sash	.	A/M L N/A	Y				
C #	Cellar Win Sill	.	A/M L N/A	Y				
	Cel Win Sash	.	A/M L N/A	Y				
	Cel Win Frame	.	A/M L N/A	Y				
	Screen Frame	.	A/M L N/A	Y				
C #	Cellar Win Sill	.	A/M L N/A	Y				
	Cel Win Sash	.	A/M L N/A	Y				
	Cel Win Frame	.	A/M L N/A	Y				
	Screen Frame	.	A/M L N/A	Y				
C #	Cellar Win Sill	.	A/M L N/A	Y				
	Cel Win Sash	.	A/M L N/A	Y				
	Cel Win Frame	.	A/M L N/A	Y				
	Screen Frame	.	A/M L N/A	Y				
C #	Cellar Win Sill	.	A/M L N/A	Y				
	Cel Win Sash	.	A/M L N/A	Y				
	Cel Win Frame	.	A/M L N/A	Y				
	Screen Frame	.	A/M L N/A	Y				
C	Foundation	0.0	L N/A	Y				
	Bulkhead	0.5	A/M L N/A	Y				
	Fences	0.0	A/M L N/A	Y				
	Shutters	.	A/M L N/A	Y				
C	Newel post	.	A/M L N/A	Y				
	Railing Cap	.	A/M L N/A	Y				
	Handrail	.	A/M L N/A	Y				
	Balusters	.	A/M L N/A	Y				
	Lower Rail	.	A/M L N/A	Y				
	Treads	.	A/M L N/A	Y				
	Risers	.	A/M L N/A	Y				
	Stringer	.	A/M L N/A	Y				
	Lattice	.	A/M L N/A	Y				
C	Drain Pipes	.	L N/A	Y				
	Elec Conduit	.	L N/A	Y				
	Oil Fill Pipe	.	L N/A	Y				
	Overhang Trim	.	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:
- Shed 0.0 mg/cm2
- deck around aboveground pool 0.0 mg/cm2

Excluded Surfaces: Surfaces listed in this box can be made intact only by a licensed deleader

SIDE A	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	IC DATE	IC METH
A				
A				
A				
A				

Soil Test Results
(Must be less than 400 ppm for play area / 1200 ppm for bare soil)

LOCATION	AREA MEASUREMENT (Square Feet)	RESULT (PPM)	REMED DATE	REMED METH
Play Area				
Bare soil				

Comments:

Christine Caulfield | **M-1950** | Christine Caulfield | 02/22/10
Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic# | Signature | Date

Address of Property: 275 Mechanic St. Apt. # — City: Marlborough

EXTERIOR D Side

SIDE D	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
D	Siding Lower	0.0	L N/A	Y				
	Corner Boards	/	L N/A	Y				
	Lower Trim	/	L N/A	Y				
	Upper Trim	5.6	L N/A	Y				
	Win Above 5'	VR	L N/A	Y				
	Porch Above 5'	/	L N/A	Y				
TO RM 4 D 1 2 3 4	Storm Door	0.0	A/M L N/A	Y				
	Door	/	A/M L N/A	Y				
	Door Casing	0.1	A/M L N/A	Y				
	Door Jamb	0.0	A/M L N/A	Y				
	Threshold	0.0	A/M L N/A	Y				
	Kickplate	NC	A/M L N/A	Y				
D 1 2 3 4	Storm Door	/	A/M L N/A	Y				
	Door	/	A/M L N/A	Y				
	Door Casing	/	A/M L N/A	Y				
	Door Jamb	/	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
	Kickplate	/	A/M L N/A	Y				
D 1 2 3 4	Door	/	A/M L N/A	Y				
	Door Casing	/	A/M L N/A	Y				
	Door Jamb	/	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
D # 1	Window Sill	CW	A/M L N/A	Y	to Room 1			
	Win Casing	CW	A/M L N/A	Y				
	Window Sash	VR	A/M L N/A	Y				
D # 2	Window Sill	0.0	A/M L N/A	Y	to Room 4			
	Win Casing	0.0	A/M L N/A	Y				
	Window Sash	0.2	A/M L N/A	Y				
D #	Window Sill	/	A/M L N/A	Y				
	Win Casing	/	A/M L N/A	Y				
	Window Sash	/	A/M L N/A	Y				
D	Lamp Post	/	L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:
Shingles above 2nd floor windows test 5.9 mg/cm2 (L)(Y)

SIDE D	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
D #	Window Sill	/	A/M L N/A	Y				
	Win Casing	/	A/M L N/A	Y				
	Window Sash	/	A/M L N/A	Y				
D #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	A/M L N/A	Y				
	Cel Win Frame	/	A/M L N/A	Y				
	Screen Frame	/	A/M L N/A	Y				
D #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	A/M L N/A	Y				
	Cel Win Frame	/	A/M L N/A	Y				
	Screen Frame	/	A/M L N/A	Y				
D #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	A/M L N/A	Y				
	Cel Win Frame	/	A/M L N/A	Y				
	Screen Frame	/	A/M L N/A	Y				
D #	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	A/M L N/A	Y				
	Cel Win Frame	/	A/M L N/A	Y				
	Screen Frame	/	A/M L N/A	Y				
D	Foundation	0.1	L N/A	Y				
	Bulkhead	/	A/M L N/A	Y				
	Fences	/	A/M L N/A	Y				
	Shutters	/	A/M L N/A	Y				
D	Newel post	/	A/M L N/A	Y				
	Railing Cap	/	A/M L N/A	Y				
	Handrail	/	A/M L N/A	Y				
	Balusters	/	A/M L N/A	Y				
	Lower Rail	/	A/M L N/A	Y				
	Treads	0.2	A/M L N/A	Y				
	Risers	0.1	A/M L N/A	Y				
	Stringer	0.0	A/M L N/A	Y				
	Lattice	/	A/M L N/A	Y				
D	Drain Pipes	/	L N/A	Y				
	Elec Conduit	/	L N/A	Y				
	Oil Fill Pipe	/	L N/A	Y				
	Overhang Trim	/	A/M L N/A	Y				

Excluded Surfaces: Surfaces listed in this box can be made intact only by a licensed deleader

SIDE A	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	IC DATE	IC METH
A				
A				
A				
A				

Soil Test Results
(Must be less than 400 ppm for play area / 1200 ppm for bare soil)

LOCATION	AREA MEASUREMENT (Square Feet)	RESULT (PPM)	REMED DATE	REMED METH
Play Area				
Bare soil				

Comments: