

From the Director's Desk

Demolition has been completed on the library site. The 1960s addition has been taken down, and all that's left is the 1904 Carnegie building. The demolition revealed the remaining structure of the Palladian window on the east side of the Carnegie. The design calls for this window to be restored so that, whether you are driving east or west on West Main Street, your view will include one of these stately windows.

The concrete footings for the new addition have begun to be poured. The weather must cooperate before the pourings proceed. Luckily, we have had some warmer days that have made progress in this area possible.

The construction workers are also grinding up the rocks on the site to use as landfill. This saves the cost of trucking the loads of rocks off site.

Scaffolding has been added to the Carnegie building façade so that workers can closely evaluate the terra cotta and assess what needs to be repaired.

Despite it being winter, the construction team is on schedule and making progress every day!



Margaret Cardella